


Half Gable Cap

24 GA - SMP 1911011
26 GA - SMP 1911012
24 GA - PVDF 1911013



$\frac{1}{12} = 94^\circ$	$\frac{7}{12} = 116^\circ$
$\frac{2}{12} = 98^\circ$	$\frac{8}{12} = 120^\circ$
$\frac{3}{12} = 102^\circ$	$\frac{9}{12} = 124^\circ$
$\frac{4}{12} = 105^\circ$	$\frac{10}{12} = 128^\circ$
$\frac{5}{12} = 109^\circ$	$\frac{11}{12} = 132^\circ$
$\frac{6}{12} = 112^\circ$	$\frac{12}{12} = 136^\circ$

